The Sterling Series

Microgrooved Sandwich Type Garage Doors



A durable yet high value door for commercial applications. **Sterling** sections are 2" thick with steel inside and outside skins. The core is filled with your choice of Polyurethane or Expanded Polystyrene for added rigidity and insulating value. Optional windows are comprised of full 1" thick insulated glass with tough injection molded frames. Available in your choice of White, Almond or Sandstone.



The Sterling Series







Sandstone

White

Almond

Window Options

Windows are 1" thick insulated glass with injection molded frames.

Sizes available are 24"x6", 24"x12" and 34"x16".



Sterling Models Available

Model 400– Sandwich type with an R-9 Polystyrene core Model 500– Sandwich type with an R-16 Polyurethane core

Specifications

- Heavy duty hardware for dependable operation.
- Sections are 2" thick in 18", 21" or 24" height.
- Widths available 8', 9', 10', 12', 16' and 18'.
- Heights Available 7' to 14' in 6" increments.
- •Track Systems— Standard lift, vertical lift, high lift, dual track low headroom, clip angle, full angle or bracket mount.

Kevmar Lifetime Limited Warranty

Kevmar hereby warrants the Sterling door sections for as long as the original end user (homeowner) owns the home the doors were installed in, against any structural failure causing the door to become inoperable.

All factory applied finishes are warranted for a period of three years against any defects in material and workmanship. Kevmar will not be responsible for any customer applied finishes or coatings.

All Kevmar supplied hardware is warranted for a period of (3) three years from date of purchase.

In the event the doors are defective, send a claim to: Keymar Mfg. 188 E CR 600 N. Arthur, IL 61911 Within (15) days of discovery of the suspected defect.

After notification, Keymar shall then be permitted to inspect the doors, and upon verification of the defect, will repair or replace at it's option the defective doors.

This warranty excludes any and all damages caused by scratches, exposure to chemicals, fumes, condensation, fire, improper use, negligent operation, improper installation, lack of mainte nance, or damages resulting from causes beyond the manufactures control.

Keymar shall not be responsible for any incidental or consequential damages arising out of any breach of this express limited warranty. Warranty does not cover any field labor costs. This Warranty supersedes and replaces all warranties previous to 10/01/17

